



Type: Initial accreditation



Certificate of Accreditation

This is to certify that

OZMA NIGERIA CO LTD
No 78 Apala Street, off Giwa-amu
Okumagba Layout - Warri-Delta state

Has been assessed by the Nigeria National Accreditation System and meets the requirements of the International Standard

ISO/IEC 17020:2012

with demonstrated technical competence in the field of

Inspection

for the specific services listed on the approved Scope of Accreditation.

On behalf of the Nigeria National Accreditation System:



Inspection
No. IN 002

Issue date: June 21, 2022
Validity through: June 20, 2024

Scope of Accreditation

Name of Inspection Body
OZMA Nigeria Co Ltd
No 78 Apala Street, off Giwa-amu
Okumagba Layout - Warri-Delta state

Schedule No.: IN 002

Issue No. 1: 21 06, 2022

Valid to: 20 06, 2024

S/N	Inspection Item	Type of Inspection	Reference Documents (in-house procedures/rules/regulations)
Lifts and lifting mechanisms			
1	Lifting, rigging and hoisting equipment	<ul style="list-style-type: none">- QA/QC Inspection/Third Party Inspection Services.- Qualitative Inspection (NDT: Radiographic Testing, Ultrasonic Inspection, Magnetic Particle Testing & Dye Penetrant Testing)	Procedure for the provision of QAQC Inspection services, Radiographic Testing Procedure, Ultrasonic Testing Procedure, Magnetic Particle Testing Procedure, Dye Penetrant Testing Procedure, ASME V, ASME B31.3, API 1104, AWS D1.1, SNT-TC-1A.
Pipeline and related facilities			
2	Welds Pipelines Process, Mechanical, Electrical and Instrument Installations, Structural and Civil Materials	<ul style="list-style-type: none">- QA/QC Inspection/Third Party Inspection Services.- Qualitative Inspection (NDT: Radiographic Testing, Ultrasonic Testing, Magnetic Particle Testing & Dye Penetrant Testing)	Procedure for the provision of QAQC Inspection services, Radiographic Testing Procedure, Ultrasonic Testing Procedure, Magnetic Particle Testing Procedure, Dye Penetrant Testing Procedure, ASME V, ASME B31.3, API 1104, AWS D1.1, SNT-TC-1A.